

# AIRCRAFT MAINTENANCE RECORDS

**N** 3905T

## PROP LOG BOOK



# AIRCRAFT MAINTENANCE RECORDS

Owner PRECISION FLIGHT SERVICES


Aircraft Registration **N** 3905T

Manufacturer HARTZELL

Model HC-C341Z-11ZF/F7283

Serial No. 044141A

Position CENTER



# AIRCRAFT MAINTENANCE RECORD

Page No. \_\_\_\_\_

**CA  
FOR**

PROP MODEL HC-C3YR-1RF/F7283  
PROP S/N DY4141A  
REG NO N3905T  
WORK ORDER 1534-03-2020

**SouthCo Aviation LLC**

3602 Thunderbird Road  
Houma, La 70363  
Phone 985-868-7858

1 of 1

DATE 3/30/2020  
A/C TSN 6072 9  
PROP TT  
TSPOH 1013 6  
TACH 1051 8

K

## Prop Entries


Performed Annual Inspection IAW FAR Part 43 Appendix D using PA28R-180 inspection checklist a guide.

## Maintenance Release

The aircraft and/or component(s) on N3905T was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1534-03-2020, Dated 3/30/2020

DATE: 3/30/2020

SIGNED:



Work Order: 1534-03-2020


Gavin Gravois, IA 2714799

Printed by EBis 3 (datcomedia.com)

**SOUTH COAST PROPELLER SERVICE, INC.**  
5750 DUROSE DRIVE, BESSEMER, AL 35022  
205-426-7022  
REPAIR STATION #S6PR302X

DISASSEMBLED, CLEANED & VISUALLY INSPECTED. REPAIRED AS NECESSARY.  
DRESSED BLADES & PAINTED. REASSEMBLED & GREASED, SET ANGLES,  
TRACKED AND BALANCED. THIS WAS THE ONLY WORK PERFORMED.

WORK ORDER # SR-14084  
MODEL # HC-C3YR-1RF  
BLADE MODEL # F7282  
HUB SERIAL# DY4141A  
DATE: 02/09/2021



JAMES M. GAITHER,  
GENERAL MANAGER

**SOUTH COAST PROPELLER SERVICE, INC.**  
5750 DUROSE DRIVE, BESSEMER, AL 35022  
205-426-7022  
REPAIR STATION #S6PR302X

GOVERNOR PARTIALLY DISASSEMBLED, CLEANED & FLUSHED.  
PARTS VISUALLY INSPECTED FOR WEAR. REPLACED SEALS  
AND GASKETS. REASSEMBLED, BENCH CHECKED AND  
FUNCTION TESTED.

WORK ORDER # SR-14074  
MODEL # F-2-7A  
SERIAL # 2517W  
DATE 02/17/2021



STEPHEN ROSE,  
CHIEF INSPECTOR

**SUB-TOTAL** THIS PAGE

**TOTAL** - CARRY FORWARD TO NEXT PAGE

PROP MODEL HC-C3YR-1RF/F7283  
PROP S/N DY4141A  
REG NO N3905T  
WORK ORDER 1733-04-2021

**Precision Flight Service, INC.**

126 Jack Pine Lane  
Ponchartroula, La 70454  
Phone 504-909-9022

DATE 3/29/2021  
A/C TSN 6087  
PROP TT 1027.7  
TSPOH 1027.7  
TACH 1065.9

No. \_\_\_\_\_  
**WORK**


**Prop Entries**

Removed Propeller and Governor Reinstalled after IRAN inspection by South Coast Propeller. WOF SR-14084 (Prop) and SR-14074 (Gov).

**Maintenance Release**

The aircraft and/or component(s) on N3905T was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1733-04-2021. Dated 3/29/2021.

DATE: 3/29/2021

SIGNED: 

Work Order: 1733-04-2021

Colton Lobitz, A&P 3849387

Printed by EBIS 3 (datcomedia.com)

PROP MODEL HC-C3YR-1RF/F7283  
PROP S/N DY4141A  
REG NO N3905T  
WORK ORDER 1733-04-2021

**Precision Flight Service, INC.**

126 Jack Pine Lane  
Ponchartroula, La 70454  
Phone: 504-909-9022

DATE 5/11/2021  
A/C TSN 6091.7  
PROP TT 1032.4  
TSPOH 1032.4  
TACH 1070.6


**Prop Entries**

Performed Annual Inspection IAW FAR Part 43 Appendix D using PA28R-180 inspection checklist a guide

**Maintenance Release**

The aircraft and/or component(s) on N3905T was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 1733-04-2021. Dated 5/11/2021.

DATE: 5/11/2021

SIGNED: 

Work Order: 1733-04-2021

Colton Lobitz, A&P 3849387

Printed by EBIS 3 (datcomedia.com)

5/11/2021		<p><b>"I certify that this <u>REPAIR</u> has been inspected in accordance with <u>AN/ANNUAL</u> inspection and was determined to be in airworthy condition"</b></p> <p><i>Colton Lobitz A&amp;P 20546571A</i></p>
FF 1032-4		

PROP MODEL HC-C3YR-1RF/F7283  
PROP S/N DY4141A  
REG NO N3905T  
WORK ORDER 2019-06-2022

**Precision Flight Service, INC.**

126 Jack Pine Lane  
Ponchartroula, La 70454  
Phone 504-909-9022

DATE 6/23/2022  
A/C TSN 6117.5  
PROP TT 1058.2  
TSPOH 1058.2  
TACH 1096.4


**Prop Entries**

Performed Annual Inspection IAW FAR Part 43 Appendix D using PA28R-180 inspection checklist a guide.

**Maintenance Release**

I certify that this aircraft and/or component(s) on N3905T was inspected in accordance with an Annual Inspection and approved for return to service. All work was performed in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 2019-06-2022. Dated 6/23/2022.

DATE 6/23/2022

SIGNED: 

Work Order: 2019-06-2022

Colton Lobitz, IA 2649387

Printed by EBIS 3 (datcomedia.com)

**SUB-TOTAL THIS PAGE**

**TOTAL - CARRY FORWARD TO NEXT PAGE**

# AIRCRAFT MAINTENANCE RECORD

Page No. \_\_\_\_\_

Date	Total Time	DESCRIPTION OF WORK PERFORMED
		SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORMING WORK

**CAR FORW**

1 of 1

PROP MODEL: HC-C3YR-1RF/F7283  
 PROP S/N: 0Y4141A  
 REG NO: N3905T  
 WORK ORDER: 2344-09-2023

**Precision Flight Service, INC.**  
 126 Jack Pine Lane  
 Ponchatoula, La 70454  
 Phone 504-909-9022

DATE: 5/17/2024  
 A/C TSN: 6167.2  
 PROP TT: 1107.9  
 TSPOH: 1107.9  
 TACH: 1146.1

**Prop Entries**

Performed Annual Inspection IAW FAR Part 43 Appendix D using PA28R-180 inspection checklist a guide.

**Maintenance Release**

I certify that this aircraft and/or component(s) on N3905T was inspected in accordance with an Annual Inspection and approved for return to service. All work was performed in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 2344-09-2023, Dated 5/17/2024.

DATE: 5/17/2024

SIGNED: \_\_\_\_\_

Colton Lobitz, IA 3849387

Work Order: 2344-09-2023

Printed by EBIS 3 (datcomedia.com)

2827-05-2025 (07-08-2025)

Page 1 / 1

MAKE: Piper  
 MODEL: Pa-28R-180  
 S/N: 28R-30239  
 REG. NO: N3905T  
 PROP MAKE: HARTZELL  
 PROP MODEL: HC-C3YR-1RF/F7283

**Precision Flight Services, INC.**  
 126 Jack Pine Lane  
 Ponchatoula, La 70454

W/O #: 2827-05-2025  
 DATE: 07-08-2025  
 A/C TT: 6254.0  
 A/C Tach: 6232.9  
 Prop TSPOH: 1194.7  
 Prop TT: 1194.7

**Propeller Entries**

(3) Performed Annual Inspection IAW FAR Part 43 Appendix D using PA28R-180 inspection checklist a guide.

**Maintenance Release**

I certify that this aircraft and/or component(s) on N3905T was inspected in accordance with an Annual Inspection and approved for return to service. All work was performed in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair facility under Work Order No. 2827-05-2025, Dated 07-08-2025.

DATE: 07-08-2025

SIGNED: \_\_\_\_\_

Colton Lobitz  
 A&P or IA Number: 3849387

WORK ORDER: 2827-05-2025

Printed by EBIS (EBIScloud.com)

**SUB-TOTAL THIS PAGE**

**TOTAL - CARRY FORWARD TO NEXT PAGE**