
## PROPELLER ASSEMBLY LOG

PROPELLER ASSEMBLY LOG					
PAGE	NUMBER	₹	_		ga esta an a sa a sa a sa a sa a sa a sa a s
Dațe	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
23 18		500	D3A34C401-C [80148	NEW AT McCAULEY PROPELLER SYSTEMS. INSPECTED AND FOUND TO BE AIR- WORTHY ON THIS DATE.	6050F
A 8					
5 - A					a was a second s
			4 1 2 2 3 4 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		6

	PRO	PELLER ASSEMBLY	LOG	
AGE	NUMBER		Control of the Contro	
Date		ALLEYA		∍ 8 te r
	1413 East Main Street, Clarksv	fille Ar 72830 . 479-243-66	04 . www.pvaviation.com	-
	Date: 09/03/18 Registration #: N6328E	Model: D3A34C401 Tach: 1891.1	Serial Number: 180148 TTSN: "0"	
	Installed this propeller on N6328 ground operational and leak chec		e with STC # SA00413WI. All	W 2.1
	I certify this propeller has been in determined to be in airworthy con		Annual Inspection and was	_
4 4	SignedVer	non Hampton A&P43141795	55IA	_
	The second of th	*	4	
		Y William I I I I I I I I I I I I I I I I I I I	100 d	
			The transfer of the control of the c	



					Q.	
	Make:	McCauley		Reg No.:	N6328E	
	Model:	D3A34C401	PROMINENT	Date:	1/24/2020	
PAG	Serial No.:	180148	HANCOCK	W/O No.:	1288	
	AFTT:	1965.9	PROP MAINTENANCE ENTRY	Tach:	1965.9	
	TSNEW:	<b>2</b> 4.8	v.Gd=r		1	ture &
	1	0:	aisterion de Mainten	ane :	1 02	ficate
Dat∟	The state of the s	rt-magenti-	Description of Work Accomplishe	d.tory	- 1/1	nber
	,	and dressed bl	ades as needed. roper operation.			
	Inspections	Completed:				
	<ul><li>Complied current FAR</li></ul>		100HR/Annual Inspection IAW man	ufacturer's ins	tructions and	-
			Approval for Return to Service			
			repaired and inspected in accordance with			3
		rworthy and is app under this work or	roved for return to service. Pertinent detail	ls of the work pe	rformed are on file	

Joseph B Averett 2740243 IA/AP Phone: (225) 800-2359 Fax: (225) 224-6211

Email: info@hancockaviation.com Web: www.hancockaviation.com

**Authorized Signature** 

Hancock Aviation LLC 4421 Chuck Yeager Avenue Baton Rouge, LA 70807

			Reg No.:	N6328E	
Make:	McCauley D3A34C401 180148		Date:	4/9/2021	
Model: Serial No.:		HANCOCK	AVIATION		
	2013.0	PROP MAINTENANCE ENT	RY Tach:	2013.0	
AFTT:	A STATE OF THE STA	TSNEW: 121.9		) p (40) a to attribute	,

# Description of Work Accomplished.

### Work Completed:

- \* Inspected and dressed blades as needed.
- \* Inspected Governor for proper operation.

#### **Inspections Completed:**

\* Complied with Propeller 100HR/Annual Inspection IAW manufacturer's instructions and current FARs

### **Approval for Return to Service**

The article identified above was repaired and inspected in accordance with current FAA regulations and was found to be airworthy and is approved for return to service. Pertinent details of the work performed are on file at this agency under this work order.

**Authorized Signature** 

Joseph B Averett 2740243 IA/AP

Hancock Aviation LLC 4409 Chack Yeager Avenue Baton Rouge, LA 70807

Email: info@hancockaviation.com Web: www.hancockaviation.com

Phone: (225) 800-2359 Fax: (225) 224-6211

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
			2	I certify that this I spele has been inspected in accordance with a loo hr.
				inspected in accordance with a zoshr.
			,	inspection and was determined to be
				inspection and was determined to be in airworthy condition. Date 6/19/23 Tach Time 2684hr. Total Timehr.
				Robert A. Davis Jr
	· · · · · · · · · · · · · · · · · · ·			Robert A. Davis Jr.
	**************************************	A	#	
	**************************************		5 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	A CONTRACTOR OF THE CONTRACTOR
		Acceptance is a		
			* · · · · · · · · · · · · · · · · · · ·	
	• • • • • • • • • • • • • • • • • • •			
		*	4	
			A state of the same of the sam	
+		W 10	4	
	- 1			
			8 7 7	
y 10 % at 0				
Tolkhouse the second se			2	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
2 1		20 00 H 10 10 10 A	2 2	
		entrancopyrius d	y	
		E-management	Supplementary of the state of t	SUB-TOTALS this page
1		Service Servic	\$5-decomposition in	TOTAL S_Carry forward to next need