

N1551F

SANTA FE

AERO SERVIC

121 Aviation Dr. • Bldg 4002 • Santa Fe

N1551F 09/24/2019 Hobbs- 1871.6 TSNEW-361.5

Performed a 100 hr Inspection in accordance with FAR 43 appendix "D".

1. Checked prop heat wires and cleaned brushes and brush block.

I certify this propeller was inspected in accordance with a 100 hr Inspection and was determined to be in an airworthy condition.

Smiling Aviation, Inc.

870 15.75 Road

Delta Co 81416

Chad Dawson

A&P 3432546

970-874-5181

Date: 7/17/2017 Make: HARTZELL Model: HC-H3YF-11

Tach: N/A Hobbs: 1718.5 TTP: 208.7

C/W A 100 HOUR INSPECTION IAW FAR43 APPENDIX D ITEMS AND REFERENCING HARTZELL MM. RESEARCHED AD'S THROUGH 7/15/2017.

• BLENDED MINOR NICKS IN PROP BLADES AND PAINTED BLADE FACES.

• LUBRICATED HUB WITH FRESH A/S 6 GREASE.

GROUND RAN ENGINE OPS AND LEAK CHECK SATISFACTORY.

This Engine has been inspected IAW a 100 Hour Inspection and has been determined to be in airworthy condition and is approved for return to service.

Gerardo Ontiveros

A&P28193561A

Work accomplished at Santa Fe Aero Services, LLC. Reference work order # SO-17-0214

N1551F

Propeller Log

PROPELLER LOG ENTRY

07/16/2021

N1551F

Tach 2036.3

TT 735.2

Completed 100 hour inspection per Appendix D to Part 43. This aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this repair station under Work Order 23991. I certify that this propeller has been inspected in accordance with a(n) 100 hr. inspection and was determined to be in an airworthy condition.

Signed: 
signature of authorized representative

Rite-Way Aviation, Inc.
Repair Station YWYR832L
7814 Eagle Lane, Spring, TX 77379

Date: 7/17/2017 Make: HARTZELL Model: HC-H3YF-1RF S/N: LX626B

Tach: N/A Hobbs: 1718.5 TTP: 208.7 TTP=HOBBS-1509.8

C/W A 100 HOUR INSPECTION IAW FAR43 APPENDIX D ITEMS AND REFERENCING HARTZELL MM. RESEARCHED AD'S THROUGH 7/15/2017.

• BLENDED MINOR NICKS IN PROP BLADES AND PAINTED BLADE FACES.

• LUBRICATED HUB WITH FRESH A/S 6 GREASE.

GROUND RAN ENGINE OPS AND LEAK CHECK SATISFACTORY.

This Engine has been inspected IAW a 100 Hour Inspection and has been determined to be in airworthy condition and is approved for return to service.

Gerardo Ontiveros

A&P28193561A

Work accomplished at Santa Fe Aero Services, LLC. Reference work order # SO-17-0214

N1551F

DATE 10/06/2020

Tach- 1986.30

TSMOH- 476.50

Performed a 100 hr Inspection in accordance with FAR 43 appendix "D".

I certify this propeller was inspected in accordance with a 100 hr Inspection and was determined to be in an airworthy condition.

Smiling Aviation, Inc.


870 15.75 Road

Delta Co 81416

Steven A. Charlesworth

A&P3659378

970-874-5181

	1410 Jet Stream Drive, Suite 100 Henderson, NV 89052 Phone: 702-735-2739	A/C Reg: N1551F
		A/C SN: 41721
CRS# 9VNR950B	WO: N1551F-MXP-6275	Prop TT: 686.3
Prop: Hartzell HC-H3YF-1RF	Prop SN: LX626B	Position: NA

ACTT 2196.1 Prop Overhauled 10/8/2012

Performed annual inspection IAW Hartzell MM and Cessna 400 AMM and checklist 5-20-00. OK.
Removed and reinstalled propeller to perform nose wheel strut repair which required engine removal.
Reinstalled propeller using new O-ring P# C-3317-228 and new nuts P# A-2044. Operationally checked and found OK at this time.

I certify that this propeller has been maintained / inspected I/A/W manufacturers maintenance manual and the requirements of 14 CFR part 43 and was determined to be in airworthy condition. pertinent details are on file under WO 6275.

Richard A. Wengien:  12/5/2022

Make:	Hartzell		Reg No.:	N1551F
Model:	HC-H3YF-1RF		Date:	1/13/2023
Serial No.:	LX626B		W/O No.:	1945
AFTT:	2210.4		Hobbs:	2210.4
	TSN:			
	700.6			

Description of Work Accomplished.

Work Completed:

* Inspected & Dressed Prop as needed.

Inspections Completed:

* Complied with Propeller **100HR/Annual Inspection** IAW manufacturer's instructions and current FARs

Approval for Return to Service

The article identified above was repaired and inspected in accordance with current FAA regulations and was found to be airworthy and is approved for return to service. Pertinent details of the work performed are on file at this agency under this work order.

Authorized Signature



Joseph B Averett 2740243 IA/AP

Hancock Aviation LLC
4409 Chuck Yeager Avenue
Baton Rouge, LA 70807

Phone: (225) 800-2359 Fax: (225) 224-6211
Email: info@hancockaviation.com
Web: www.hancockaviation.com

Make:	Hartzell		Reg No.:	N1551F	
Model:	HC-H3YF-1RF		Date:	2/29/2024	
Serial No.:	LX626B		W/O No.:	2317	
AFTT:	2271.9	PROP MAINTENANCE ENTRY		Hobbs:	2271.9
TSN: 762.1					

Description of Work Accomplished.

Work Completed:

* Inspected & Dressed Prop as needed.


Inspections Completed:

* Complied with Propeller 100HR/Annual Inspection IAW manufacturer's instructions and current FARs

Approval for Return to Service

The article identified above was repaired and inspected in accordance with current FAA regulations and was found to be airworthy and is approved for return to service. Pertinent details of the work performed are on file at this agency under this work order.

Authorized Signature



Joseph B Averett 2740243 IA/AP

Hancock Aviation LLC
4409 Chuck Yeager Avenue
Baton Rouge, LA 70807

Phone: (225) 800-2359 Fax: (225) 224-6211
Email: info@hancockaviation.com
Web: www.hancockaviation.com