

N1957Y

2 of more



SANTA MONICA PROPELLER

Propeller Logbook

3135 DONALD DOUGLAS LOOP S, SANTA MONICA, CALIF. 90405-6186
PHONE #: 1-800-421-9995
FAA ARS ZY2R362L

PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. No. _____

Blade Ser. Nos. _____

No 1 _____

No 2 _____

No 3 _____

No 4 _____

No 5 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

RIGHT ENGINE

Hub Model B3D36 C474E

Blade Design 74 SA-G

Diameter _____

Hub Ser. No. 951419

Blade Ser. Nos. _____

No 1 PC 013

No 2 PC 016

No 3 PF 035

No 4 _____

No 5 _____


PITCH RANGE

High 33.7 Low 9.7

Feather N/A Reverse N/A

Governor Model _____

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
4/8/99	W.O.# 66232	PROPELLER COMPLETELY OVERHAULED, L.A.W. McCAULEY SERVICE MANUAL # <u>761001</u>. ALL A.D.'s AND McCAULEY S.B.'s AND SLS COMPLIED WITH TO DATE.	
T.T.S.O.	0.00		
		THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER THIS INVOICE NUMBER AND DATE	
		SIGNED	
		AUTHORIZED SIGNATURE F.A.A. A.R.S. NO.ZY2R362L	